



INFORCE SECURITY CORP.

DIGITAL VIDEO RECORDING AND SURVEILLANCE
BURGLAR, SMOKE AND INTRUSION DETECTION

INTERNET ROUTER CONFIGURATION

Your existing Internet router must be configured to open the following static port numbers in order for the respective surveillance system components to operate correctly. Please contact your network administrator or I.T. personnel before programming your router.

- 📠 WebCam: 80
- 📠 MultiView: 4550, 5550
- 📠 ViewLog: 5552
- 📠 Vital Sign Monitoring: 5610
- 📠 Remote Admin: 7424, 7425
- 📠 3G / QuickTime / Mac: 8554, 17300 → 17380
- 📠 iPhone, Blackberry, Smartphone: 8866, 5511

Alternate programming method for routers that use port ranges

- 📠 80, 4550→5610
- 📠 7424→7425
- 📠 8554→8866
- 📠 17300→17380

EMAIL to SMS alerts

- 📠 Telus Subscribers: yournumber@msg.telus.com
- 📠 Fido Subscribers: yournumber@fido.ca
- 📠 Rogers Subscribers: yournumber@pcs.rogers.com
- 📠 Bell Subscribers: yournumber@txt.bell.ca

ISP Technical Support Numbers

- 📠 **Cogeco:** 905-333-5433 **Rogers:** 1-888-764-3771 **Bell:** 1-877-877-2426
- 📠 **Sympatico:** 310-7873 **Teksavvy:** 1-877-779-1575

Inforce Security Corp. Technical Support

- 📠 **Web:** <http://www.inforcesecurity.com/support.htm>
- 📠 **Email:** getsupport@inforcesecurity.com
- 📠 **Telephone:** 1-888-667-6115